	er ID 64814 nber 16, 2010 2:14:52	PM	- h								Page 1
Revision ID: tem Name:		ety: 6.00 Qty: 6.00		Accept	Cust Item II			IIII s	Setup Star	! !!!!!!!!!!	
Reference:	Process Plan:QC:	fl Date		Tooling: SPC (Y/N):		te:		F	tun Star Sto		
Sequence ID/ Work Center ID		tion		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D3640 00 Bandsaw easpa Bandsaw	Rev A BAND SA	Memo Cut blank 4.700 " loi	ng	0.00	10/12/20			9			
10 HAAS 1 HAAS CNC vertical		IC VERTICAL MACHI Memo 1- Mill as per Folio F. rad intersection with	A670 & Dwg D364	0.00 0.00 I0 Rev: Д □2-De	burr and Blend	Ioliz	123	6			
20 QC Quality Control	QC2- Insp	ect parts off machine Fa	AJ/FAIB	0.00	10/12/22			_ <i>i</i> e_	- J	•.	

t

W/O:			W	ORK ORDER CHANG	ES					F
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
									Prod Mgr	
<u> </u>										
Part No	•	PAR #:	Fault Cate	egory:	NCR	: Yes N	No DQA	:	Date:	
	R	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
		Description of NC Section A	Corrective Action Section				Verification		Approval	Approval
DATE	STEP		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
										,
										

Work Order ID 64814

Thursday, December 16, 2010 2:14:52 PM



Page 2

Item ID:

D3640-1

Accept



Setup Start

Stop



Revision ID:

Item Name:

Belt Guide

Start Date:

12/16/2010

Start Qty: 6.00

Required Date: 12/21/2010 Req'd Qty: 6.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

____ Date:

Tooling: Date:

SPC (Y/N):

Date:

Tool ID

Date:

Tool # Plan

Code

Start

Reject

Qty

Stop



Number Stamp

Insp.

Sequence ID/ **Work Center ID**

130

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours**

0.00

Accept

Qty

140

Packaging

Packaging

Identify as per dwg & Stock Location: 243

Memo

0.00

0.00

0.00

Reject

150

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Dail 10	. oopaoc									4	
W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	t	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							 				
Part No	:	PAR #:	Fault Categ	jory:	_ NCR: Ye	s No	DQ.	A :	_ Date: _	1	
Resolution:		Disposition	1:	QA: N/C	Clos	ed:		Date: _			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)					
DATE	STEP	Description of NC	<u></u>		veri			fication Approva		Approval	
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	ion Sign & Date		Secti	on C	Chief Eng	QC Inspector	
		-							<u> </u>		

Picklist Print

Thursday, December 16, 2010 2:14:56 PM

Work Order ID: 64814

Parent Item: D3640-1

Larent Item Name: Belt Guide



Start Date: 12, 16/2010

Required Date: 12.1/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev:A New Issue 07-01-15 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MDELRINB0.75X1.250		Purchased	No			100	f	27.9024	0.4	2.526316			
										11	0/12/2	O	

Delrin Bar

 Location
 Loc Oty
 Loc Code

 MAT050
 27.9024

14535 27.9024

2.6

	•												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHAI	NGE	E	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	•	PAR #:	Fault Cate	gory:	_ NCR:	Yes N	io DQ	A:	Date:				
Resolution:			Disposition	1:	_ QA: N	I/C Clo	sed:		Date: _				
NCR:			WORK ORDI	ER NON-CONFORMA	ANCE (NCR)							
DATE	STEP	Description of NC	Corrective Action Section			<u></u>		cation	Approval	Approval			
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector			
						-							
										1			
				·									
:													


DART AEROSPACE LTD	Work Order:	44814
Description: Belt Guide	Part Number:	D3640-1
Inspection Dwg: D3640 Rev: A		Page 1 of 1

	FIRST ARTICLE INSPECTION CHECKLIST										
	Х	First Artic	le _	Proto	otype						
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Cor	nments				
4.50	+/-0.030	4.501			1101 N - SI-	3					
0.8ა	+/-0.030	.803			~						
0.13	+/-0.030	.129			,						
0.31	+/-0.030	. 311			در						
0.200	+/-0.010	200									
0.40	+/-0.030	393									
0.03 x 45°	+/-0.030 x 0.5°	.03X45°	./								
0.23	+/-0.030	- 229									
0.40	+/-0.030	.401									
0.625	+/-0.010	. 632									
R0.13	+/-0.030	.125									
Measured by:		Audited by:	and		Prototype A	nnroval:	N/A				
	6/B/23	Date:		23	1 Tototype A	Date:	N/A				
			101101	<u>*</u>	Povio						
	Change New Issue				Kevis KJ/EC	ed by	Approved				
											

H-\FORMS\Ouality	Assurance\annroved	OA\FAI revD

W/O:			WORK ORDER CHANGES							
DATE	STEP	PRO	OCEDURE CH	CEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									,	
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date:		
· 	R	esolution:	Disposit	ion:	_ QA: N/C C	losed:		Date: _		
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCI	₹)				
DATE	CTED	Description of NC		on B	Verifi	cation	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector	
. 4										
	·									
						ļ				

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



-										ι
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			>				· · ·			
Part No	:	PAR #:	Fault Cate	gory:	NCI	R: Yes I	No DQA	۸:	Date: _	
Resolution:			Disposition	n:	QA:	N/C Clo	sed:	· · · · · · · · · · · · · · · · · · ·	Date: _	
NCR:			WORK ORD	ER NON-CONFORM	IANCE	(NCR))			
DATE	STEP	Description of NC Section A			ction B		Verific	ation	Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
									,	
										-
							:			
						·		•		